

# UL Warns of Potentially Hazardous Oil-Filled Space Heaters

**NORTHBROOK, Ill., - May 28, 2008** - Underwriters Laboratories (UL) is notifying consumers and retailers that oil-filled space heaters manufactured by the China Singfun Electric Group Co., Ltd. may pose a risk of fire. These heaters do not comply with UL requirements and are not eligible to bear the UL Mark.

**Name of Product:** Maxi-Heat Oil-Filled Space Heater, model 70001

**Units:** Unknown quantity

**Manufacturer:** China Singfun Electric Group Co., Ltd.

**Date of Manufacture:** August 2001 to present

**Product Identification:** The space heater has a label with an unauthorized UL Mark for the United States and Canada and the following information:

**LISTED**  
E218087  
MADE IN CHINA  
**MAXI-HEAT**  
OIL FILLED HEATER  
RADIATEUR A BAIN B'HUILE  
MODEL/MODELE 70001

**Hazard:** The heaters may be filled with oil that has been found to be unsuitable for use in space heaters. The oil has a low flash point, which may pose a risk of fire.

**What You Should Do:** UL recommends consumers stop using these space heaters immediately and return them to the place of purchase.

