

March 2<sup>nd</sup>, 2009

## Globe-Electric Company Inc. Recalls 15W fluorescent Undercabinet Light

**Toronto, ON** – The Electrical Safety Authority is notifying the public that Globe-Electric Company Inc. has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

**Name of Product:** 15W Fluorescent Undercabinet Light

**Units:** 8100 in Canada.

**Manufacturer/Importer:** Globe-Electric Company Inc.

**Hazard:** It has been discovered amongst a few fixtures that once installed, heat build-up may occur.

**Incidents/Injuries:** 3 incidents reported. No injuries or damages following these incidents.

**Description/Models:** The 15W fluorescent under-cabinet lights affected are all the same model 28002 and were sold to retailers across Canada under the UL label file E203660 and with a date code 09 08. The product can be identified by a label positioned beneath the unit showing model: 28002 and factory ID: RGH (IX). This recall affects only those products with that specific label file and date code.

**Sold by:** Various retailers across Ontario and Canada.

**When was distributed:** March through June 2008.

**Manufactured in:** China

**Remedy:** Consumers who have purchased this specific unit are to contact Globe Customer Service and arrange for a product exchange.

**Consumer Contact:** Consumer service toll free number: 1-800-361-6761 or e-mail: [customerservice@globe-electric.com](mailto:customerservice@globe-electric.com).

**Remarks:** The recalled Undercabinet lights are certified to Canadian Standards by Underwriters Laboratory. For more information about Underwriters Laboratory product certification process please visit: <http://www.ul.com>.

